



HYTORC EDGE-1S & 2

PRESSURE IN PSI	PRESSURE/TORQUE CONVERSION CHART			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	178	25	241	104
1600	190	26	258	110
1800	215	30	292	124
2000	240	33	325	138
2200	265	37	359	152
2400	290	40	393	166
2600	315	44	427	179
2800	340	47	461	193
3000	365	50	495	207
3200	390	54	529	221
3400	416	58	564	235
3600	441	61	598	248
3800	467	65	633	262
4000	492	68	667	276
4200	517	72	701	290
4400	543	75	736	304
4600	568	79	770	317
4800	594	82	805	331
5000	619	86	839	345
5200	645	89	875	359
5400	670	93	909	373
5600	696	96	944	386
5800	721	100	978	400
6000	747	103	1013	414
6200	772	107	1047	428
6400	797	110	1081	442
6600	823	114	1116	455
6800	848	117	1150	469
7000	873	121	1184	483
7200	899	124	1219	497
7400	925	128	1254	511
7600	950	131	1288	524
7800	976	135	1323	538
8000	1002	139	1359	552
8200	1027	142	1393	566
8400	1053	146	1428	580
8600	1078	149	1462	593
8800	1104	153	1497	607
9000	1129	156	1531	621
9200	1155	160	1566	635
9400	1180	163	1600	649
9600	1206	167	1635	662
9800	1231	170	1669	676
10000	1257	174	1704	690

This chart supercedes all prior version regarding this tool 03/31/2008

Southwest Texas 4802 Baldwin Blvd. Corpus Christi 78408 361-888-5080	West Texas 3508 S County Rd 1290 Odessa, TX 78765 432-561-8481	Main Office 12420 Texaco Rd Houston, TX 77013 713-453-6677	Southeast Texas 2484 W Cardinal #4 Beaumont, TX 77705 409-840-9699	Central & East Texas 7900 Rodeo Trl. #500 Mansfield, TX 76063 682-334-2679
--	--	--	--	--